EXISTING CONDITIONS

1 BLUFFER'S PARK BLUE FLAG BEACH

2 RISK TO PUBLIC SAFETY

3 OUTLET AT BASE OF TRAIL

4 SYLVAN LANDSLIDE

5 SHOALS BETWEEN HEADLANDS

6 GUILD CONSTRUCTION ACCESS ROUTE

7 GREY ABBEY LANDSLIDE

8 BLUFF TOE EROSION

9 INFORMAL RISKY ACCESS

10 INFORMAL TRAILS

11 INFORMAL ACCESS AT BEECHGROVE DR

REFINED PREFERRED ALTERNATIVE

A MEADOW HABITAT

B SAND DUNE HABITAT

C SUCCESSIONAL HABITAT

D HEADLAND BEACH

E AQUATIC HABITAT ENHANCEMENTS

www.trca.ca/swp

TORONTO

Toronto and Region Conservation for The Living City